

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

1085
West
> 1
1.424 mi.
7519 ft.

MAN HOLE 44579
MAPLE AVE AND SEA GATE AVE
BROOKLYN, NY

NY Spills **S121464188**
N/A

Relative:
Higher

Actual:
0 ft.

SPILLS:

Name: MAN HOLE 44579
Address: MAPLE AVE AND SEA GATE AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1709858 / 2018-06-26
Facility ID: 1709858
Facility Type: ER
DER Facility ID: 519766
Site ID: 566324
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: D4
SWIS: 2401
Spill Date: 2018-01-29
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2018-01-29
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2018-01-29
Spill Record Last Update: 2018-06-26
Spiller Name: PAUL WALSH
Spiller Company: CON ED
Spiller Address: MAPLE AVE AND SEA GATE AVE
Spiller Company: 999
Contact Name: PAUL WALSH
DEC Memo: "01/29/18 - Lakhani 2 gallons of dielectric fluid leaked from the Esco Switch in a manhole (MH 44579). The switch is still leaking approx. five (5) drops per minute. A sample of the oil was taken to test for PCB. EMIS# 264403 6/26/18 - Austin - Con Ed did an initial cleanup on 2/15/18, removed the leaking switch on 2/20/18, then completed the cleanup on 2/22/18 - See document files for further information - Spill closed - end"

Remarks: "switch failed clean up is pending tests"

All Materials:

Site ID: 566324
Operable Unit ID: 1314254
Operable Unit: 01
Material ID: 2321831
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered:
Oxygenate:

Not reported
Not reported